



METER

APOGEE UV SENSOR

TABLE OF CONTENTS

1. Introduction.....	2
2. Installation.....	2
2.1 Set Up Mounting Assembly	4
2.2 Connect to METER ZENTRA Series Logger	5
3. Data Interpretation	6
4. Troubleshooting	6
5. Customer Support	7
6. Terms and Conditions	7
Index	8



1. INTRODUCTION

Apogee Instruments SU-221 Ultraviolet (UV) Radiation sensors are designed for continuous UV radiation measurement in either indoor or outdoor environments. The Apogee UV sensor detects UV radiation from 300 to 400 nm, which lies primarily in the UV-A portion of the UV spectrum (315 to 400 nm).

The information in this document explains how to install the required hardware to mount Apogee UV sensors that have been preconfigured by METER Group to work seamlessly with METER ZENTRA series data loggers. Details of how the ZENTRA system handles the data are also included. Please read this document carefully in its entirety before going out to the field.

For more information on Apogee sensors, please review the [Ultraviolet-A Radiation Sensor User Manual](#) or visit the [Apogee UV sensor product page](#) (apogeeinstruments.com/uv).

2. INSTALLATION

Follow the steps listed in [Table 1](#) to install Apogee sensors in the field. A cable, mounting bracket, leveling plate, and screws are included with the sensor. Other tools will need to be provided.

Table 1 Installation

Tools Needed	Wrench 13 mm (0.5 in) Flathead screwdriver Mounting post 33.0 to 53.3 mm (1.3 to 2.1 in) diameter post, pole, tripod, tower, or other similar infrastructure that extends above the canopy Mounting bracket + leveling plate Model AL-140 (included). Nylon screw #10-32 x 3/8 in (included) METER ZENTRA series data logger ZL6 or EM60 METER ZSC Bluetooth® Sensor Interface (optional) METER ZENTRA software ZENTRA Utility, ZENTRA Utility Mobile, or ZENTRA Cloud
--------------	--

Table 1 Installation (continued)

Preparation	Conduct System Check METER strongly recommends setting up and testing the system (sensors and data loggers) in the lab or office. Inspect and verify all components are intact. Visit the data logger product page for the most up-to-date software and firmware. Verify all sensors are functional and read within expected ranges. Consider the Surroundings Choose a location that allows the hemispherical view UV sensors to be above the plant canopy or in a position with an unobstructed view of the sky (such as a large canopy gap or forest clearing). Ensure the sensor is not shaded from nearby objects (weather stations, mounting posts, etc.).
Mounting	Install on Mounting Post Use the U-bolt to mount the mounting bracket and sensor assembly (Section 2.1). The U-bolt is compatible with most meteorological stands, poles, tripods, and other mounts. Ensure the sensor is oriented so the cable points toward true North (in the Northern hemisphere) or true South (in the Southern hemisphere) to reduce azimuth error. Secure the System Tighten the U-bolt nuts by hand until hand-tight, and then tighten with a wrench. CAUTION: Do not overtighten U-bolt. Adjust the three machine screws on the leveling plate until the integrated bubble level indicates that the sensor is level. Secure and Protect Cables NOTE: Improperly protected cables can lead to severed cables or disconnected sensors. Cabling issues can be caused by many factors such as rodent damage, driving over sensor cables, tripping over cables, not leaving enough cable slack during installation, or poor sensor wiring connections. Install cables in conduit or plastic cladding when near the ground to avoid rodent damage. Gather and secure cables between the sensors and the data logger to the mounting post in one or more places to ensure cable weight does not pull the plug free from its port. Connect to Data Logger Plug the sensor into a data logger. Use the data logger to make sure the sensor is reading properly. Verify these readings are within expected ranges. For more instructions on connecting to data loggers, refer to Section 2.2.

2.1 SET UP MOUNTING ASSEMBLY

Apogee UV sensors must be level to accurately measure UV irradiance incident on a horizontal surface. Each Apogee UV sensor purchased from METER comes with an AL-140 Solar Mounting Bracket with Leveling Plate. The AL-140 can be mounted to either a horizontal or vertical post, depending on which set of holes is used.

1. Align the cable M8 connector pins with the sensor M8 connector holes and seat connectors fully.
2. Tighten the cable screw until hand-tight ([Figure 1](#)).

M8 connectors are easy to overtighten. Do not use pliers or other tools to tighten this connector.




Figure 1 Attach M8 connector

3. Mount the sensor to the leveling plate ([Figure 2](#)) with the included nylon screw.




Figure 2 Apogee UV sensor installed on mast or pipe

4. Attach the leveling plate to the mounting bracket using the included three machine screws.
5. Attach the mounting bracket either to a horizontal arm ([Figure 2](#)) or vertical post using the included U-bolt.

2.2 CONNECT TO METER ZENTRA SERIES LOGGER

Apogee UV sensors are preconfigured by METER and work seamlessly with METER ZENTRA series data loggers. The sensors come with a 3.5-mm stereo plug connector (Figure 3) to facilitate easy connection with the data loggers. Apogee sensors come standard with a 5-m cable.




Figure 3 3.5-mm stereo plug connector wiring

Check the METER download webpage for the most recent data logger firmware. Logger configuration may be done using either ZENTRA Utility (desktop and mobile application) or ZENTRA Cloud (web-based application for cell-enabled ZENTRA data loggers).

1. Plug the stereo plug connector into one of the sensor ports on the logger (Figure 4).




Figure 4 Logger connection

2. Connect to the data logger via ZENTRA Utility with a laptop and USB cable or ZENTRA Utility Mobile app with a mobile device supporting Bluetooth® communication.
3. Use ZENTRA Utility to scan the ports and make sure the sensors were properly identified by the logger and are reading properly.
METER data loggers should automatically recognize the Apogee sensor.
4. Use ZENTRA Utility to set the measurement interval.
5. Use ZENTRA Utility to configure communication settings for data transfer to ZENTRA Cloud.

Sensor data can be downloaded from METER data loggers using either ZENTRA Utility or ZENTRA Cloud. Refer to the logger user manual for more information.

3. DATA INTERPRETATION

Apogee UV sensors used with the ZENTRA system report UV-A irradiance in energetic flux density units of watts per square meter (W/m^2). Additionally, the sensor orientation information is provided in the metadata tab of ZENTRA Cloud and ZENTRA Utility file downloads (Microsoft® Excel® spreadsheet). Sensor orientation is reported as the zenith angle in units of degrees, with a zenith angle of 0° indicating a sensor oriented straight upwards.

4. TROUBLESHOOTING

This troubleshooting section details possible major problems and their solutions. If the problem is not listed or these solutions do not solve the issue, contact [Customer Support](#).

Table 2 Troubleshooting

Problem	Possible Solution
Sensor not responding	Check power to the sensor and logger. Check sensor cable and stereo plug connector integrity. Check that the SDI-12 address of the sensor is 0 (factory default). Check this with ZENTRA Utility by going to Actions, select Digital sensor terminal, choose the port that the sensor is on, and send the ?I! command to the sensor from the dropdown menu.
Sensor values are not reasonable	Verify the sensor is not shaded. Verify the orientation angle of sensors.
Cable or stereo plug connector failure	If the stereo plug connector is damaged or needs to be replaced, contact Customer Support for a replacement connector or splice kit. If a cable is damaged refer to the METER wire-splicing guide for cable repair.

It is recommended that Apogee UV sensors are returned for factory recalibration every 2 years. Visit [Apogee repairs](#) (apogeeinstruments.com/recalibration-and-repairs) or contact [Apogee Technical Support](#) (techsupport@apogeeinstruments.com) for details.

5. CUSTOMER SUPPORT

NORTH AMERICA

Customer support representatives are available for questions, problems, or feedback Monday through Friday, 7:00 am to 5:00 pm Pacific time.

Email: support.environment@metergroup.com
sales.environment@metergroup.com
Phone: +1.509.332.5600
Fax: +1.509.332.5158
Website: metergroup.com

EUROPE

Customer support representatives are available for questions, problems, or feedback Monday through Friday, 8:00 to 17:00 Central European time.

Email: support.europe@metergroup.com
sales.europe@metergroup.com
Phone: +49 89 12 66 52 0
Fax: +49 89 12 66 52 20
Website: metergroup.com

If contacting METER by email, please include the following information:

Name	Email address
Address	Instrument serial number
Phone	Description of the problem

NOTE: For products purchased through a distributor, please contact the distributor directly for assistance.

6. TERMS AND CONDITIONS

By using METER instruments and documentation, you agree to abide by the METER Group, Inc. Terms and Conditions. Please refer to metergroup.com/terms-conditions for details.

INDEX

C

cables **3, 4, 5**
components **2**
connecting **5**
customer support **7**

D

data **6**

I

installation
 mounting **3, 4**
 preparation **3**
 tools needed **2**

M

mounting **3**
mounting bracket **2, 4**

R

recalibration **6**

S

stereo plug connector **5**

T

terms and conditions **7**
troubleshooting **6**

U

U-bolt **3, 4**
ultraviolet radiation **2, 4**
user manual **2**

Z

ZENTRA series data logger **2, 3**
ZENTRA software
 Cloud **2, 6**
 Utility **2, 6**
ZSC **2**

METER Group Inc.

2365 NE Hopkins Court Pullman, WA 99163
T: +1.509.332.2756 F: +1.509.332.5158
E: info@metergroup.com W: metergroup.com

METER Group GmbH

Mettlacher Straße 8, 81379 München
T: +49 89 1266520 F: +49 89 12665220
E: info.europe@metergroup.com W: metergroup.com

